


Fig. 1  
(Prior Art)



No carpet tack needed at threshold in front of the door.

Fig. 2

Threshold is set under  
the door.

Fig. 3(a)





Fig. 3(b)






Fig. 3(c)



FIXED. NOT ADJUSTABLE.

Fig. 4(a)



ADJUSTABLE DOOR BOTTOM

Fig. 4(b)




Fig. 5(a)




Fig. 5(b)




Fig. 6(a)




Fig. 6(b)




Fig. 6(c)




Fig. 6(d)




Fig. 7(a)




Fig. 7(b)




Fig. 7(c)




Fig. 7(d)






Fig. 8(a)




Fig. 8(b)




Fig. 8(c)




Fig. 8(d)




Fig. 9(a)




Fig. 9(b)




Fig. 9(c)




Fig. 9(d)




Fig. 10(a)




Fig. 10(b)




Fig. 10(c)




Fig. 10(d)




Fig. 11(a)




Fig. 11(b)




Fig. 11(c)




Fig. 11(d)






Fig. 12(a)




Fig. 12(b)




Fig. 12(c)